Wave 2-7-85

by Karl Peterson

Snow and cold weather can cause problems for photographers, especially those of us who like to get outdoors and photograph the unique scenery that winter brings. In spite of the weather some beautiful shots can be taken if we take the precautions that seem to be necessary this time of year.

The advent of current photo technology has placed a battery or two in almost every camera made and created a dependency on electrical energy in order to operate. This has proved to be a boon for photographers but has, at times, raised havoc when shooting in cold weather. When venturing outdoors then it is a good idea to keep your camera as warm as possible. The best way to do this is to hang it around your neck and zip it inside your coat or parka, taking it out to shoot and the zipping it up again. Under all but the most severe cloud in the sky and the sunlight conditions this should keep your batteries warm enough to provide metering, shutter release. and film advance. Just this simple step can mean the difference between getting the photo or a camera that won't work.

Another thing to avoid is blowing on the lens or viewfinder to clear them of that speck of dust that always seems to appear. Doing so will only put a coating of frost on the glass surface you meant to clean. Far better to carry a lens cleaning brush and use it to remove any specks or dirt.

One other item in the line of cold weather maintenance is the removal of snow from the camera. If we do get snow on it it seems to be the natural thing to just wipe it off with either our hand or a cloth. Carry a shaving

or small paint brush and just brush it off. This will prevent smearing up the camera.

Lets assume though that it is a beautiful, clear winter day. Not a

makes the snow sparkle. How many times have you taken pictures under such conditions only to have them lack the sparkle and brilliance you wanted to preserve? The problem lies in the exposure meter, either the one on our camera or a seperate one.

Any meter measures light and either sets or recommends an exposure based on an average level of illumination. Snow on a bright day is not an average level of illumination. I won't explain how or why here, but under such conditions your meter will indicate a setting that will underexpose the scene one or two stops, resulting in a photo that is darker than what you had visualized.

The cure for this is to override your meter and give one or two stops more exposure. Either shoot at the next slowest shutter speed or open up the lens another stop, i.e., from f8 to f5.6. In the case of an automatic camera set the ASA/ISO indicator at either half or one quarter the recommended film speed.

Finally, take several shots at different exposure settings. Don't be afraid to use a little film in order to get the image you want.

Photofun

Wave 21 Feb 1985

by Karl Peterson ti

Last week our discussion of exposure measurement and metering illustrated the fact that there are many photographic subjects that, for one reason or another, do not fall in the so called "average" category. In situations like this our photographs often do not turn out as well as they could. Herewith some hints on how to measure exposure more effectively and produce better photos.

an image, then it is, worth the them, tend to get in too big a hurry to shoot. The best advice in ction is the light coming from? What kind of light is it, bright receive the most emphasis. How to other elements in the scene. In other words if a subject grabs you commit yourself to making even illumination? Determine does the light affect it as opposed your attention to the extent that they see a scene that excites a situation like this is to take your ime. Sit back and closely observe the scene. What direcasting well defined shadows, or soft and diffuse creating more the primary subject that will Many photographers, when

time taken to observe it in order to produce the best photographic rendering possible.

After studying a scene and deciding what element to emphasize, it is time to meter the subject and determine the best exposure. Take an overall exposure reading and make note of it. Then, using your camera's meter or a separate hand held one, take a closeup reading of the main subject. This means walking up to it, filling the frame with the subject, and making the reading. Note where this reading falls in relation to the overall

A good rule of thumb in this transparency film, and to meter the shadows when using negorder to produce the best regard is to meter for the highlights, or brightest parts, or a scene when using slide, or the overall brightness ratio of a scene. After doing so we promises in our exposure in rendition of the primary subject. or print, film and five stops latitude for Iside. In other words if the range between the brightest and the darkest parts of those portions will be either under or overexposed. This is why it is so important to move in with your meter and determine sometimes have to make coma scene exceeds these latitudes, there is an exposure latitude of around seven stops for negative. Meter other elements in the scene, noting their relationship to one another. Bear in mind that reading you took first.

the shadows when using negative film. Sometimes it is not possible to

results.

approach a scene close enough to take the selective meter readings we would like. In this case we have to make a substitute reading of something that approximates the elements in the distant scnee. Two items can be used, one of which we all have, and the other. I strongly suggest you acquire.

The item you should get is an 18 percent gray card available in any good camera shop. This card reflects 18 percent of the light falling on it, the same amount as our "average" scene. Place this card in the same light as is falling on the distant scene and take your meter reading from it. Make sure that the card fills the viewfinder and that you are measuring only the light reflected from it.

Finally. if no gray card is available, take a meter reading from the palm of your hand, once again being careful that it is placed in the same light falling on the subject. The human palm will reflect approximately one stop more light than gray card so note the reading, and then increase your exposure by one stop. In other words if the palm reading shows f11 at 1/125 then shoot at f8 at 1/125 or f11 at

Don't be slaves to all the automatic features in your camera. Try these metering techniques. Experiment with them, metering for highlights and shadows, using a gray and the palm of your hand. I think you'll be pleased with the

Terry Reynolds

Born _	F	Place				Wife		NAME TOO O	N SUBMITTING SHEET	
Chr	F	Place				Ward 1.		NAME	V SUBMITTING SHEET	
Marr	F	Place				Examiners: 2.				
						Stake or Mission				
Bur HUSBA	AND'S FATHER	Place	HUSBAN MOTHER	D'S						
HUSB/ OTHER	AND'S R WIVES		MOTHER					RELATION OF	RELATION O	F ABOVE TO V
WIF	E								FOR FILING ONLY	
Born _										NO 🗆
								Ye to	ALOGICAL SOCIETY	
Died _	F	Place						X, W	\	_
Place								Procell ag	ORDINANCE	
	S FATHER		WIFE'S MOTHER					1 May 200	NDOWED (Date)	SEALED (D WIFE TO
WIFE'	S OTHER							lasked 29		
SEX	CHILDREN	WHEN BORN	WHER	E BORN		DATE OF FIRST MARRIAGE DA	Y WHEN DIED YE			1/////
M F	List each child (whether living or dead) in order of birth Given Names SURNAME	DAY MONTH YEAR	TOWN	COUNTY	STATE OR COUNTRY	то wном			\	SEALED (D CHILDREN
1									\	
2					-			4	\	
2								-		
3					1					
4										
5			940							
_										
6								_		
7						T				
'										
8										
					-					
9			_			<u> </u>	~~~~			The second
10										
						,				
11										
SOURCES OF INFORMATION				OTHER MA	OTHER MARRIAGES			NECESSARY EXPLANATIONS		